



Broadcast Products Technical Bulletin 20-2011-048

DATE: **May 16, 2011**SUBJECT: **PARTS REGISTRATION—AT-154D BOARD**

MODEL: **PDW-510 Series**
PDW-510P Series
PDW-530 Series
PDW-530P Series
PDW-539P Series

SERIAL NO: **ALL****DESCRIPTION**

The AT-154D board for PDW-539P series models is available as a service part:

Model	AT Board	Part No.
PDW-539P	AT-154D	A-1827-223-A

Use the correct AT board as listed in Table 1.

Table 1

Model	AT Board	Part No.
PDW-510 PDW-510P PDW-530 PDW-530P	AT-154 mounted circuit board	A-8347-368-A
PDW-539P	AT-154D mounted circuit board	A-1827-223-A

NOTE:

- The new AT-154D board differs from the AT-154 board (A-8347-368-A) previously used for all the models, including PDW-539P. The AT-154 boards currently supplied as parts no longer have software for PDW-539P and AT-154D boards do not have software for PDW-510/510P/530/530P.
- DO NOT use the current AT-154 board (A-8347-368-A) for PDW-539P; otherwise the model may not be displayed correctly or the unit may not function. In addition, boot software on the AT board must be rewritten with the MS-69B board (A-1579-146-A).
- DO NOT use the AT-154D board for PDW-510/510P/530/530P; otherwise, boot software on the AT board must be rewritten with the MS-69 board (A-8347-484-B).

ORDERING INFORMATION

To order parts online, go to: www.sony.com/servicesplus. For service or parts ordering assistance, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin 00-1999-000

PDWM11-010