



## Broadcast Products Technical Bulletin 20-2011-087

DATE: August 29, 2011

SUBJECT: **INCORRECT PART NUMBER PRINTED ON  
CN-2437 BOARD**

MODEL: **DSR-400K**  
**DSR-400L**  
**DSR-400PK**  
**DSR-400PL**  
**DSR-450WSL**  
**DSR-450WSPL**  
*DSR-600PL*  
*DSR-650WSPL*  
**DVW-970**  
**DVW-970P**  
*MSW-930P*  
**MSW-970**  
**MSW-970P**  
**PDW-510**  
**PDW-510P**  
*PDW-510P//U*  
**PDW-530**  
**PDW-530P**  
*PDW-530P//U*


SERIAL NO: **ALL**

*Italicized information in green applies to  
customers outside the United States.*

**DESCRIPTION**

An incorrect part number may be printed on some CN-2437 boards. Correct the part number as follows and as shown in Figure 1.

Incorrect	Correct
A-1139-843-A	→ A-8347-338-A

**Figure 1**

**NOTE:** The correct part number printing combination is:

A-8347-338-A ↔ 1-860-107-11