



Broadcast Products Technical Bulletin 20-2005-025

DATE: **March 21, 2005**

SUBJECT: **PROTECTOR PEELS OFF**

MODEL: **PDW-510
PDW-510P
PDW-530
PDW-530P**

DESCRIPTION

If the end of the protector is subjected to excessive physical stress, the elastomer part of the protector may peel away from the internal metal fixture. (See Figure 1.)

SERIAL NO:

PDW-510	10,001-10,240
PDW-510P	40,001-40,225
PDW-530	10,001-10,465
PDW-530P	40,001-40,550




Figure 1

PARTS REQUIRED

Part No.	Description	Qty.
3-797-064-04	Protector	1

ORDERING INFORMATION

To order upgrades or for regional service center and parts ordering information, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin *001999000*

MODIFICATION PROCEDURE

1. Remove the five +B2.6 screws, and remove the former protector.
2. Attach the new protector using the five +B2.6 screws. (See Figure 2.)




Figure 2

NOTE: The new protector has two rounded areas to ensure the elastomer remains locked in position. (See Figure 3.)




Figure 3